

# L55 SERIES INSTALLATION INSTRUCTIONS

## L55 SERIES CANOPY LIGHTING FIXTURE

### FOR USE WITHIN COMMERCIAL COOKING HOOD

#### INSTRUCTIONS

1. Ensure the fixture will be mounted a minimum of 4 feet above cooking surface.
2. For supply connections use wire rated for at least 230°F (110°C).
3. Make opening and holes for junction box. See diagram below.
4. Mount adapter plate to pre-wired junction box.
5. Thread two (2) mounting screws into adapter plate a distance of about 1/8".
6. Make electrical connections. Push all supply wiring into junction box.
7. Position housing over adapter plate and push against canopy hood sheet metal so that mounting screws protrude through large end of keyhole slots.
8. Turn housing clockwise until mounting screws rest against small end of keyhole and tighten screws.
9. Install lamp and globe.

NOT FOR USE IN DWELLING

WARNING- RISK OF FIRE.

USE 120 VOLT - 100 WATT LAMP MAX

THIS PRODUCT IS TO BE INSTALLED ONLY BY A QUALIFIED ELECTRICIAN

